

METAL CUTTING BANDSAW BLADES - ISO: 4875 Part - 2



CARBON STEEL BANDSAWS: Range

Metric : Length 30.5 Mtrs.

Width 6.5, 10, 13, 16, 19, 25mm

Thickness 0.6 mm

Inches : Length 100 ft.

Width 1/4, 3/8, 1/2, 5/8, 3/4, 1"

Choice of T.P.I. : 4, 6, 8, 10, 14, 18, 24

Grade : Carbon Steel



MIRANDA brand Metal Cutting Bandsaw Blades from MIRANDA TOOLS are available in following tooth shapes and settings.

TOOTH SHAPE



Regular Teeth

(a) Regular or Conventional Tooth: Zero rake angle is widely used for general sawing and for friction sawing.



Skip teeth

(a) Skip Tooth or Buttress Tooth: Zero rake angle is used for cutting free machining non-ferrous alloys, wood and plastic.



Raker Set

(c) Raker Set: This design has one tooth bent to the left, and another to the right, followed by one un-set tooth. This is repeated throughout the band.



Wavy Set

(d) Wavy Set: This design has the setting of the teeth in groups to the left and to the alternatively throughout the band.

Range of MIRANDA brand Metal Cutting Bandsaw Blades manufactured by MIRANDA TOOLS

NOMINAL SIZE			TEETH PER	TEETH PER INCH (TPI)		
Inches		Milimeters	Raker Set	Wavy Set		
1/4 x 0.025 (23 G)		6.35 x 0.63	10, 14	18, 24		
3/8 x 0.025 (23 G)		9.53 x 0.63	6, 8, 10, 14	18, 24		
1/2 x 0.025 (23 G)		12.70 x 0.63	6, 8, 10, 14	18, 24		
1/2 x 0.025 (23 G)	(Skip)	12.70 x 0.63	6			
5/8 x 0.032 (21 G)	` ''	15.88 x 0.80	6, 8, 10, 14	18, 24		
3/4 x 0.032 (21 G)		19.05 x 0.80	4, 6, 8, 10, 14	18, 24		
3/4 x 0.032 (21 G)	(Skip)	19.05 x 0.80	6			
1 x 0.035 (20 G)	, , ,	25.40 x 0.90	4, 6, 8, 10, 14	18. 24		

Metal Cutting Bandsaw Welded Coils

NOMINA	TEETH PER INCH (TPI)		
Inches	Milimeters	Raker Set	Wavy Set
3/4 x 0.032 (21 G) x 8' 3" 3/4 x 0.032 (21 G) x 9' 10"	19.05 x 0.80 x 2515 19.05 x 0.80 x 2997	4, 6, 8, 10, 14 4, 6, 8, 10, 14	18, 24 18. 24
3/4 x 0.032 (21 G) x 117' 1/2"	19.05 x 0.80 x 3544	4, 6, 8, 10, 14	18, 24

^{*} Welded Coils (Loops) can be supplied in any size against confirmed orders.



General Recommendations:

Work Thickness in inches	1/8"	1/4"	1"	2"	1/8"	1/4"	1"	2" & Over
Material to be cut		F	Pitch T.P.I.			Cutting	Speed Fee	et/Minute
Free machining steel	18	14	10	6	250	200	175	150
Mild Steel	24	14	10	6	250	200	175	150
Carbon Steel	24	14	10	6	250	200	175	150
Annealed Tool & Alloy Steel	24	18	10	6	100	80	60	40
Alloy Construction Steel	24	14	10	8	175	150	125	100
High Speed Steel	24	14	10	8	150	100	75	50
Stainless Steel	24	14	10	8	100	75	50	50
Tubing	24	14	-	-	175	150	-	
Grey Cast Iron	18	14	10	6	200	150	100	75
Malleable Cast Iron	18	14	8	6	200	175	150	125
Meehanite	18	10	8	6	150	100	75	50
Copper		10	8	6	-	1500	1500	1500
Aluminum	18	10	6	6	1800	1400	800	600
Phosphor Bronze	18	14	10	6	1200	900	700	700
Plastic	18	10	8	6	1500	2000	1500	1500
Asbestos	18	10	8	6	4000	3500	3000	3000
Phenolic	18	10	8	6	4500	4000	3500	3000
Paper	18	10	8	6	1500	1500	1500	1500
Rubber (Hard)	18	10	8	6	4000	3800	3000	3000

Feed Rate Chart:

Feed Rate : Linear inch per minute						
Work Thickness	1/4"	1/2"	1"	1-1/2"	3"	6"
Carbon Steel	4.50	2.12	1.00	0.62	0.31	0.12
Cold Rolled Mild Steel	9.00	4.00	1.75	1.12	0.50	0.25
Cast Iron	16.00	7.50	3.25	2.12	1.00	0.43
High Carbon, High-Chrome Steel	2.25	1.00	0.50	0.25	0.12	0.03

Trouble Shooting:

Problem	Cause	Remedy
1. Teeth Ripping	Teeth too coarse	Check if higher TPI saw is required
1. Teetif Kipping	Excessive Feed / Load	Decrease to recommended pressure/load
	Excessive reday Loda	Check spring tension of blade
		On vertical machines, the work is hand-fed,
		Feeding pressure should be moderate and steady.
	Gullets filling up	Use thicker cutting oil
	Vibrating Work Piece	Clamp and level securely
		A slight movement of the piece causes the teeth to rip out
		On vertical machines, as the work is hand-fed, adequate
		experience and care is required to feed the work with steady pressure, at the same time without causing
		vibration. Advice screw feed wherever possible.
Excessive blade breakage	Teeth too coarse	Check if higher TPI saw is recommended.
Z. Z	Excessive tension	Reduce tension
	√Very heavy feed	Decrease to recommended pressure/load
		(15 kg. on horizontal M/c.)
	Misaligned guides	Adjust guides.
	Very high speed	Decrease to recommended speed.
	Lack of coolant	Always use cutting coolant
3. Early teeth wear	Weld not annealed Teeth too coarse	Annual the weld satisfactorily. Use a finer tooth blade
J. Larry teetir wear	Very high speed	Decrease to recommended speed
	Too light a feed	Increase to recommended pressure/load
	Lack of coolant	Always use cutting oil/coolant
4. Blade twisting	Cut is binding the blade	Decrease pressure/load
	Excessive blade tension	Decrease the tension
	Guides too close to work	√Widen gap between guides.